GOVERNMENT OF ARUNACHAL PRADESH
OFFICE OF THE ASSISTANT ENGINEER PHE & WS SUB-DIVISION
SEIJOSA

No. AE/PHESD/SJA/ESTT-26/2016-17/29 **Dated, Seijosa, the 28th September'2026**

WATER AND SANITATION CERTIFICATE

1. **School Information**
   Govt. Higher Secondary School, Seijosa
   Pakke Kessang District, Arunachal Pradesh
2. **System Description**
   - Water Supply System: Domestic Water supply
   - Water Source: PHE Supply (Public Health Engineering Dept)

3. **Supply, Hygiene & Safety Compliance**
   - 24*7 water supply: Yes
   - Drinking water safe: Yes
   - No cross connection: Confirmed
   - Adequate Pressure: Yes
   - No water stagnation: Confirmed
4. **Water Quality Test**

Parameter	Result	Limit	Status
Ph	7.2	6.5-8.5	OK
Turbidity	0.14 NTU	< 5NTU	OK
TDS	40 mg/l	<500 mg/l	OK
E Coli	Absent	0	OK
Residual Chlorine	0.2 ppm	0.2-0.1 ppm	OK

5. **Sanitation description**
   - Septic tank system
   - Capacity of 200 users
   - No leakage and foulage: confirmed
6. **Drainage Description**
   - Closed drainage: Confirmed
   - Storm water Drain availability: confirmed

Assistant Engineer
PHE&WS S-Division
Seijosa

Assistant Engineer
PHE & WS Sub-Division
Seijosa